B2900 Cable connector


nominally

tools

Connect


use manual

- Thanks you buy and use this product
- In order to use this product correctly, pls study carefully before use it.
- After study, pls keep it in the place where can find it any time.
- the insertion loss of $\leq 0.10 dB$; return loss $\leq -40 dB$; repeat on (> 5):



Instructions






- 1. Accordingly the cable choose the match-able product
- 2. pls guarantee the construction environment in allowed range
- 3. If not accordingly this manual, all responsibility should be bear by yourself.
- 4. Damage cable will harmful to human being, pls deal with correctly.
- 5. Any tools not including it, pls take it by yourself




Accordingly the tupe, choose the 250 sleeve

Under the part of 0.25mm, though 250 sleeve






1. Accordingly the chart cut 0.9mm cable, keep the naked cable with 13mm




1-1:Put the 0.9mm cable with the 0.9mm hole


steps




1-2: After the cable in the end, withstand two part ,press the gland ,then finish. steps




1-3: Use repeat opening device, withstand the gland



Accordingly the chart cut 0.25mm cable, keep the naked cable with 11.5mm



2-1: Put the 0.25mm cable with the 0.25mm hole 2-2: After the cable in the end, withstand



two part ,press the gland ,then finish.



2-3: Use repeat opening device, withstand the gland